



FIG. 1

86277-1-956T60








FIG. 4





FIG. 5






FIG. 7




FIG. 8







FIG. 9










FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG 25




FIG 26

~ 164

"F"

"G"

"H"

"I"

~ 166
"A"

"B"

"C"

"D"

0519364-1198
06277-4956T50

162

~ 168

1	2 ABC	3 DEF	CANCEL "E"
4 GHI	5 JKL	6 MNO	CORR "K"
7 PQRS	8 TUV	9 WXYZ	Blank "L"
Blank "M"	0	.	OK "J"

FIG 27




FIG 28




FIG 29




FIG 30

FIG 31

09193564.11798

